

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

January 24, 2001

CERTIFIED RETURN RECEIPT 7000 0520 0021 7482 8487

Joe Dunlop Resource Design Solutions, Inc. P.O. Box 1178 Riverton, Utah 84065

Re: Small Mine Exceeding Five Acres of Disturbance, Resource Design Solutions, Inc., RDS 502 61-& 62, S/023/066, Juab County, Utah

Dear Mr. Dunlop:

On December 8, 2000, we informed you by certified letter that your RDS 61 & 62 site has exceeded the status of a small mine. Current surface disturbance has been GPS surveyed at 6.65 acres. You were informed of two options you could choose in order to remedy the situation: 1) immediately reclaim the excess acreage to five or less acres, no later than January 10, 2001; or 2) post a \$25,000 transition surety within 30 days and submit a complete large mine application within 60 days.

On January 9, 2001, Larry Garahana of the Bureau of Land Management and Tom Munson of this Division, inspected the project area (inspection memo attached) to determine if the required reclamation had been completed. It was discovered that the work was never completed, but rather additional mining and grading had occurred since the last Division inspection. During a January 12, 2001 telephone conversation, you informed Mr. Munson that you were working on getting a bulldozer to finish the regrading and reseeding to bring the site down to less than five acres and, therefore, remain under the small mine status.

The Division will grant an extension to February 16, 2001, in order for you to complete the necessary regrading and seeding to reduce onsite disturbance below five acres. If this work is not satisfactorily completed by that deadline, we will be forced to initiate formal enforcement action as outlined in our December 8, 2000 letter.

Page 2 Joe Dunlop S/023/066 January 26, 2001

If you have any questions or concerns with this letter or you cannot meet this deadline, please contact me, or Tom Munson immediately at (801) 538-5286 and 538-5310 respectively. Thank you for your assistance in resolving this matter in an expeditious manner.

Sincerely,

D. Wayne Hedberg

Permit Supervisor

Minerals Regulatory Program

ih

Attachment: 1/9/2001 inspection memo

cc: Larry Garahana, BLM (UTU-075857)

S23-66-.ltr

833



Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

801-538-7223 (TDD)

January 23, 2001

TO:

Minerals File

FROM:

Tom Munson, Senior Reclamation Specialist F

RE:

Site Inspection, Resource Design Solutions, RDS 67 & 62, Juab County, Ut

10

Date of Inspection:

January **9**, 2001

Time of Inspection:

11:30 a.m.

Conditions:

Sunny

Participants:

Larry Garahana, BLM; Tom Munson, DOGM

Purpose of Inspection: To inspect site to determine if reclamation has been done to bring the status back down to less than five acres

It appears they have not reclaimed, but have done more mining and pulled out more blocks of granite. In more recent conversations since our initial inspection with Joe Dunlop, he stated that the bulldozer that was out there was not his and he would not be able to use it. Instead, he would have to get his friends bobcat to do the reclamation. It is felt this is not a feasible option and a bulldozer is needed to complete the regrading work.

Photos were taken of the site.

S23-66-ins.doc

JB DOGM S/023/066	1/24/01
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. Article Addressed to: JOE DUNILOP 	A, Received by (Please Print Clearly) C Signardre Agent Addressee D. Is delivery address different from item 1? If YES, enter delivery address below:
RESOURCE DESIGN SOLUTIONS INC PO BOX 1178	
RIVERTON UT 84065	3. Service Type
Article Number (Copy from service label)	
7000 0520 0021 7482 8487	
PS Form 3811 July 1999 Domestic Ret	urn Receipt 102595-99-M-1789